

Weott CSD's Operator's Report
01-14-2026 (Covering 11/13/25 to 01/14/26)
Greg Teasley & Curren Black

Springs/Flow:

- As of today 1/12 we still have good flow on B line. A line has no flow due to the last heavy rains.
- We've been to the springs twice recently and found both filters to be partially if not completely plugged.
- We believe that we have all but just a few items needed to be able to hook up the lower spring on the A side and Curren and I are planning a trip across the river as soon as possible.

Test Results:

- Water quality has been passing state standards.

Water Plant:

- It has been working efficiently.
- The problem with the automatic transfer switch for generator power really needs to be addressed ASAP.
- Also the electric pump on the B side, that allows us to pump water to the B tank and in rare cases, such as now, to the A tank needs replacing.
- One of the dosing pumps had to be rebuilt ..done.
We do need to purchase
some more rebuild kits
to have on hand though.

Wastewater Plant:

- It is passing tests and there are no new malfunctions.
There is a form seam in
the bed in use that has a
pretty significant leak.
And to repair will require
the removal of some of
the filtering gravel.
Dan and I have talked
and he said, there might
be a possibility that he
could bring Garberville's
vacuum truck to help
facilitate this task, but

will need the boards
approval for the cost.

Lift station:

- Both pumps are working as they should be.
- But the counter for the cycles on the lead pump has stopped working. I priced one, and it's gonna be about two or three hundred dollars to replace. But I need the board's approval to order one.
- I had to replace the belt on the air compressor pump that is, inside the lift station control panel.

Repairs & Leaks

- After relocating, a meter on Weott heights road, the resident has complained of low water pressure. I made a point of telling him that his pressure would be reduced due to the additional nineties in his water service line. The resident has recently inquired though, if anything could be done about it.